SECRET

1067 AUG 9 1.8 202

OUT62826

25X1	SECRET 091820Z CITE			7
	PRIORITY	DISTRI	BUTTON	
	IDEALIST SUBJ: EVALUATION OF MISSION C237C	No.	Office	Action
25X1	ATTN:	2	os	
	1. CAMERA 232 WAS USED ON MISSION C237C FLOWN ON 20 JUNE 196	7.	SEC BR	
	PROCESSING WAS ACCOMPLISHED IN THE FIELD. 2. ORIGINAL NEGATIVE:		TDS	
	A. THE RESOLUTION IS FAIR AND THE DENSITY IS HEAVY, APPARE	NTLY	EDD	
	DUE TO OVEREXPOSURE. B. 9R SIDE: THERE IS EDGE STATIC AND FRILLING ALONG THE		Ро 1-30	
	OUTBOARD EDGE INTERMITTENTLY THROUGHOUT THE ENTIRE MISSION. IT		CB_	
	IS MORE PRONOUNCED AT THE BEGINNING AND END OF THE MISSION. ABRASIONS OF UNDETERMINED ORIGIN ARE PRESENT FROM FRAME 1725 TO	7 11-	TID	
	THE END OF THE MISSION (FRAME 2354). HEAT SPLICES ARE PRESENT			
*	AS A RESULT OF EDITING.		PAG E-AXY-4	
	C. 9L SIDE: EDGE STATIC IS PRESENT ALONG THE OUTBOARD EDG- OF THE FIRST 325 FRAMES. THERE ARE NUMEROUS PINHOLES OF UNDETER	MINE	SPAD	
	ORIGIN IN THE LAST 25 FRAMES OF THE MISSION.	· •	DIA AP	
	D. BOTH SIDES: THE FRAME COUNTER IS INCORRECT THROUGHOUT THE ENTIRE MISSION. THERE IS SOME IMAGE SMEARING NOTED THROUGHO	UT " "		
•	THE MISSION THAT IS ATTRIBUTED TO VEHICLE MANEUVERING. MODE ONE	4		
	WAS USED THROUGHOUT THE MISSION. THE FIRST 21 FRAMES WERE EDITED AND FRAME NUMBER 022 IS TITLED FRAME 001. THE NEGATIVES WERE	י ע		
	COMPARED WITH MISSION C177C WHICH USED THE SAME CAMERA. THE			
	NEGATIVES FROM C237C CONTAIN HIGHER DENSITY AND DO NOT APPEAR TO BE AS SHARP. THE CYCLE RATE IS 4.5 SECONDS AND OVERLAP BETWEEN			
	VERTICAL FRAMES IS APPROXIMATELY 60 PERCENT.			
	3. POSITIVE: A. PI SUITABILITY IS FAIR, PROBABLEY DUE TO THE OVEREXPOSE	n .		_
	NEGATIVES. THERE IS NO SIGNIFICANT DIFFERENCE IN THE REPRODUCTION	ONS		7
25X1	RECEIVED FROM AND THE COPY RECEIVED FROM THE FORWARD AREA	•		
	B. PRINTING AND PROCESSING ARE GOOD. C. CLOUDS OBSCURE APPROXIMATELY 35 PERCENT OF THE MISSION.			
	SECRET			
	END OF MESSAGE			
			1	25X1

NGA Review complete

SECRET

GROUP 1
Excluded from automatic
downgrading and
declassification